

ALS Group USA, Corp.

10450 Stancliff Rd. Suite 210 Houston, Texas 77099

Certified Product Listing

For:

Drinking Water System Components - Health Effects

Company:

American Granby, Inc. 7652 Morgan Road Liverpool, NY 13090, United States

Plant Location:

Gresik-Jatim, Indonesia

Standards:

NSF/ANSI/CAN 61 - 2022 NSF/ANSI 372 - 2022

Certificate:

Issued Date: 08/12/2019

Material/Product:

Fittings & Pipes Related

Contact Temperature:

23 ± 2°C

Models:

CVMXLNL100BS: CHECK VLV BRASS MXF XL 1 IN NL CVMXLNL125BS: CHECK VLV BRS MXF 11/4 IN NL CVXLDNL100BS: CHECK VALVE BRASS XL 1 IN NL CVXLDNL125BS: CHK VALVE BRASS XL 11/4 IN NL HVBAD75NL: VAC BRKR AUTO DRN ASSE1011 NL



