

ALS Group USA, Corp.

10450 Stancliff Rd. Suite 210 Houston, Texas 77099

Certified Product Listing

For:

Drinking Water System Components - Health Effects

Company:

Polycoat Products 14722 Spring Avenue Santa Fe Springs, CA 90670-5108, United States

Plant Location:

Santa Fe Springs, CA, United States

Standards:

NSF/ANSI/CAN 61 - 2022 NSF/ANSI 372 - 2022

Certificate:

Issued Date: 09/11/2024

Material/Product:

PC Grout II LV - Crack Filler Polyurethane Grout

Contact Temperature:

23 ± 2°C

Models:

PC Grout II LV

The crack filler should not exceed more than 5% coverage of the total surface area.







10450 Stancliff Rd. Suite 210 Houston, Texas 77099

Material Characteristics:

Minimum tank size (gallons): 1000

Maximum tank surface area/volume ratio (sq in/L): 5.7

Is additional coating required (e.g. top coat, primer, intermediate coat)? (Y/N): Refer to

manufacturer instructions for details

Final cure time: 24 hours @ ambient temperature

Mix ratio: 10:1:1

Is this paint/coating system intended to be applied to a pipe? (Y/N): No

Additional comments:

The crack filler should not exceed more than 5% coverage of the total surface area.



